



Black and Decker LI4000 Outer Casing Replacement

This guide will demonstrate and explain the steps in removing the casing of the screwdriver in order to replace and fix internal components.

Written By: Bryan Beard



INTRODUCTION

The basic steps of replacing the casing of the Black and Decker LI4000 rechargeable screwdriver can be achieved in three steps which will be explained in this guide. There are a few terms that will be used throughout this guide that should be understood beforehand. There are three decals, or stickers as they will be referred to in this guide, that need to be removed before taking out the casing screws. These stickers include the Black and Decker symbol found on one side of the screwdriver, the warning label found in the exact opposite side of the screwdriver as the Black and Decker symbol, and lastly a small sticker found on the bottom of the screwdriver that displays the UL certification. Each of these stickers must be removed as they each conceal a casing-removal screw or because they lie on the seam of the casing. Next, there are eight screws that will need to be removed in order to remove then entire casing. These are the main concepts that you should be familiar with before beginning disassembly.



TOOLS:

- [Phillips #1 Screwdriver](#) (1)
 - [Heavy-Duty Spudger](#) (1)
 - [2.5 mm Hex Bit](#) (1)
-

Step 1 — Outer Casing



- Remove the stickers found on the bottom and sides of the LI4000, using a spudger.

Step 2



- Remove all six of the 12-mm long case screws with a Philips #1 Screwdriver. These screws can be found on the side of the LI4000 with the "Warning" sticker.

Step 3



- Remove the two screws that are 4-mm Hexagonal #2.5. These are very small case screws that can be found underneath the two stickers from Step 1.

Step 4



! When working with electronics, it's important to choose a tool that's ESD-safe to avoid accidental damage to the device. The metal spudger is great when you need serious prying power, but the regular black nylon spudger or a plastic opening tool should be used whenever possible.

- Pry on the seam as shown with a Spudger, in order to get the top casing loose.
- Pull the two sides apart while making sure the side that you are removing is the one with all of the case screw holes.
- i** It is good practice to remove the top connection of the battery as shown in the third image, as this will be the first step to replacing any of the components for this screwdriver.

To reassemble your device, follow these instructions in reverse order.

This document was last generated on 2017-07-07 11:48:58 AM.